SECRET

PRIORITY

1968 MAR 13 04 04 Z

Declassification Review by NGA OUT 64575 DISTRIGUTION Action Cy ivo. Onice Filo 130351Z MAR 68 Caule Sec. FM NPIC WASHDC TO DIA PPAB BT CRFT CITE NPIC 3007. Socurity 25X1 S-0134-XX-2, 23 FEBRUARY 1968 TSSG EVALUATION OF MISSION BU Q00623 FLOWN 3 SEPTEMBER 1967. 1115 THIS MISSION EMPLOYED CAMERA NUMBER 25 IN VEHICLE NUMBER PSG PROCESSING WAS ACCOMPLISHED BY THE 7TH AIR FORCE. H-21. EVALUATION OF ORIGINAL NEGATIVE: 150 EXPOSURE/RESOLUTION: THE DENSITY RANGES FROM GOOD TO UNDEREXPOSED AND THE RESOLUTION VARIES FROM GOOD TO POOR. IMAGERY AT THE LEADING (TAKE-UP) END OF ALL FRAMES IS LOW IN CONSTRAST AND APPEARS UNDEREXPOSED. THE TRAILING (SUPPLY) ENDS OF THE VERTICAL FRAMES CONTAIN IMAGERY OF GOOD CONTRAST AND EXPOSURE. THE OBLIQUE POSITION FRAMES SHOW THIS SAME TENDENCY BUT THE AREA OF DEGRADATION IS GREATER AND MORE SEVER. ANOMALY IS READILY DETECTABLE BY NOTING THE RESOLUTION, CONTRAST AND APPARENT EXPOSURE IN AN AREA OF CULTURAL IMAGERY AT THE LEADING EDGE OF A FORMAT AND THEN OBSERVING THE SAME AREA AS IT CHANGES Advance Copy LOCATION IN A SUBSEQUENT FORMAT DUE TO FORWARD MOTION OF THE Sauticad A GOOD EXAMPLE CAN BE FOUND ON FRAMES 593, 597 VEHICLE. With Test ABOUT 40 TO 50 PERCENT OF THE IMAGERY IS DEGRADED ON ALL FRAMES THROUGHOUT THE MISSION. THE APPEARANCE SUGGESTS A VEILING DUE TO CONDENSATION, ICE OR OTHER FOREIGN MATTER ON PORTIONS OF THE WINDOWS. CAMERA OPERATION: A SERIES OF PLUS AND MINUS DENSITY STREAKS ORIENTED PARALLEL TO THE DIRECTION OF SLIT TRAVEL ARE PRESENT THROUGHOUT THE MISSION. IT IS POSSIBLE SUCH STREAKS MAY BE CAUSED BY AN UNEVENNESS OF THE SLIT EDGE. MINOR BANDING PARALLEL TO THE MINOR AXIS OF THE FILM APPEARS AT THE LEADING SUCH BANDING USUALLY INDICATES ERRATIC SLIT END OF ALL FRAMES. TRAVEL. THIS ANOMALY ALSO APPEARS OCCASIONALLY IN OTHER PORTIONS OF THE FRAME BUT NO PATTERN OF REPETITION WAS DETECTED. C. OTHER DEGRADATIONS: MINOR EMULSION SCRATCHES, LIFTS AND DIGS APPEAR RANDOMLY THROUGHOUT THE MISSION. THE LAST TITLED FRAME IN THE MISSION IS 1224. 3. EVALUATION OF DUPLICATE POSITIVE: A BAND OF MINUS DENSITY APPROXIMATELY ONE INCH WIDE AND LOCATED THREE INCHES FROM THE DATA BLOCK EDGE OF THE FILM PARALLELS THE FILM EDGE (INCLUDING AREAS BETWEEN FRAMES) THROUGH-OUT PART ONE OF THE DUPLICATE POSITIVES. PRINTING AND PROCESSING

END OF MESSAGE

ARE OTHERWISE SATISFACTORY.

CONDITION OF THE IMAGERY.

THE ENTIRE MISSION.

GP-1

SECRET

Excinded from automatic downgrading and feclassification



C. CLOUDS DEGRADE OR OBSCURE APPROXIMATELY 30 PERCENT OF

B. PI SUITABILITY IS GOOD TO POOR DUE TO THE VEILED